

Evonco Distribution Limited
111 Eglinton Avenue East, Suite #200
Toronto, Ontario M6M 2V6
Telephone (416)482-5566
Fax (416)482-6655

Attention : Mr. H. Prupas

RE: HALEX COIL MAGNETIC FILTRATION SYSTEM

Dear Howard:



As you may recall, we commenced testing your device in October 1994 on a new installation in a ferrous foundry. Our personnel were surprised and encouraged at seeing the entire outer surface of the magnetically charged engine filter covered with a fine "ferrous" fuzz. We felt confident that the magnetic field was potentially trapping more ferrous contaminants than the filter could do this on its own. This dramatic visualization of the effectiveness of your system, encouraged our belief that definitely something was happening within the filter and the engine oil fluid.

As Yale is a leader in the forklift equipment business, I felt the net benefit to Yale's reputation was worth expanding our "test" to include all of our rentals and guaranteed maintenance equipment. I hope that even this minor improvement in filtration could invariably lead to longer engine life, therefore increasing the confidence in Yale's overall equipment reliability. Our maintenance personnel have had no difficulty in working with the Halex Coil and to this point we have experienced no problems. I expect that our results will appear more tangible in the future, the more we incorporate your product on our fleet.

Yours sincerely,

A handwritten signature in black ink that reads "Michael Ferry". The signature is written in a cursive style with a large, sweeping flourish at the end.

Michael Ferry
Parts Manager (Woodbridge)

MJF/cf