

LIPROD PTY. LTD.

GENERAL ENGINEERS & MAINTENANCE CONTRACTORS

2 WALLIS STREET,
EAST MAITLAND 2323

PHONE : (049) 33 1549

Paul Everitt
Regional Sales Manager
Dellran Corporation Pty Ltd
54 Goldingham St
Tenambit 2323
N.S.W.

RE: Halex Magnet Coil Trial


Dear Paul,

I was pleased to trial your Halex Magnetic Coil on my 2WD off road racer at the last Round of the Nationals at Goondiwindi Queensland on the weekend of the 26 to 27 October 1996.

My car completed only 150km of the event when the clutch failed and I had to retire from the event. Upon returning to base we removed the filter canister and Halex Magnetic Coil and cut it open to check the ferrous contamination collected.

We could not believe the amount of ferrous metal that the Halex Coil removed, my off road racer will not race without a Halex Coil in future.

Yours faithfully,


Barry Johnson
Open 2WD class 1
Owner / Driver

19 November 1996

